

Procedure to Access Heidelberg Prosetter Usage Data

-- From the GUI of the machine (on RIP or Tiff Catcher)

- Go to Device and choose Recorder

-- Next choose Operator Counter to get:

- Material Counter
- Plate Counter
- Exposing Counter
- Sum of Material Used
- Total Plate Count
- Sum of All Exposures
- Sum of All Punches
- Sum of Power On Time
- Sum of Exposure Time